

Weller Summary Soldering Tips



Soldering Tips

Soldering Tools	XT Page 172 / 173	XTR Page 175	LTR Page 182	ET Page 184	XHT Page 176	XNT Page 168 / 169	RT Page 164 / 165	RTW Page 166 / 167	LT Page 177/ 178/179/180	NT Page 170	LHT Page 183	HT Page 185	WTA Page 185	PT Page 166 / 187	CT Page 188/189/190	SPI Page 191	DS Page 195	DX Page 194	F Page 198	R Page 198	D Page 199	Q Page 199	NR Page 200	ND Page 201	NQ Page 202	NQT Page 283	XDS Page 197	GO Page 192	70 Page 193	71 Page 192	XT soldering head Page 173 / 174					
Fast response																																				
WP 65	Page 142																																			
WP 120	Page 144																																			
WP 200	Page 145																																			
WXP 65	Page 142																																			
WXP 120	Page 143																																			
WXP 200	Page 145																																			
Silver-Line																																				
FE 75	Page 138/148 / 126																																			
FE 80	Page 138, 149, 126																																			
MPR 80	Page 147																																			
WP 80	Page 146																																			
WSP 80	Page 146																																			
WSP 150	Page 147																																			
Active-Tip																																				
WMRP	Page 140																																			
WMRT	Page 141																																			
WXMP	Page 140																																			
WXMT	Page 141																																			
Standard-Line																																				
LR 21	Page 148																																			
LR 82																																				
WTA 50	Page 158																																			
Unregulated Line Voltage Soldering Irons																																				
SPI 16,27,41,81	Page 152, 153																																			
Magnastat Controlled Line Voltage Soldering Irons																																				
TCP5,TCP 12,TCP 24	Page 158																																			
W 61,101,201	Page 151																																			
Desoldering Irons																																				
DS 22,80,DSV 80																																				
DSX 80	Page 154																																			
DXV 80	Page 155																																			
WXDP 120	Page 157																																			
DSX 120	Page 157																																			
WXDV 120	Page 155																																			
Hot Air Irons																																				
HAP 1,HAP 200	Page 158 / 159																																			
HAP 3000	Page 70																																			
WXHAP 200	Page 158																																			
Gas Powered Soldering Irons																																				
Pyropen Jr.	Page 43																																			
Pyropen and P. Piezo	Page 42																																			
WP 60	Page 43																																			
Inert Gas Soldering Irons																																				
WSP 80IG	Page 37																																			
WSP 120IG	Page 37																																			
Heating Elements																																				
HER 120	Page 35																																			
HER 80	Page 35																																			